

Strata CIX40 Hardware Change Notice

Toshiba has made hardware modifications to the Strata CIX40 cabinet and power supply. These changes improve Strata CIX40 power supply operation and grounding. The new Strata CIX40 R3 cabinet will still use the same GCTU2A processor, but the motherboard is now labeled as GMAU4.

The capacities, features, and pricing have not changed.

Hardware Changes

- AC Adapter - AC cord, different DC output voltage, and shorter DC cord.
Note Note: R1/R2 power adapters do not work on R3 cabinets and R3 adapters do not work on R1/R2 cabinets. The DC plugs are different sizes precluding use in the wrong cabinet.
- The card slot guide plates have been extended in the top portion of the cabinet.
- Please note the following pages in the CIX40 R3 Installation Manual for examples.
 - 1-10 a view of the Strata CIX40 R3 cabinet interior
 - 1-27 and 1-28 Compare the GMAU3 and the GMAU4 motherboards

There will be no changes to the current pricing but please note the new part numbers for the cabinet and CIX40 system package.

New Part Numbers	Description
CHSU40A3-SYS	CIX40 4 x 8 cabinet, system processor, and power adaptor
CHSU40A3	CIX40R3 Cabinet

Toshiba will begin shipping the new CIX40R3 hardware later this month.

Important! As always, all Strata CIX systems sent in for repair must include the power supply.

[Link to the Strata CIX40R3 installation manual on Toshiba's FYI web site.](#)